



NO. N86-4-1-4

To the following Permittee or Operator:

Name GENERAL COAL COMPANY, INC.Mine CRANDALL CANYON☐ Surface☒ Underground☐ OtherCounty EMERYState UTAH

Telephone _____

Mailing Address P.O. Box 1201 HUNTINGTON, UT 84527State Permit No. ACT/015/032

Ownership Category

☐ State☐ Federal☐ Fee☒ MixedDate of inspection FEBRUARY 27,19 86Time of inspection 4:00☐ a.m.☒ p.m. to6:30☐ a.m.☒ p.m.

Operator Name (other than Permittee) _____

Mailing Address _____

Under authority of the Utah Coal Mining and Reclamation Act, Section 40-10-1 et seq., *Utah Code Annotated*, 1953, the undersigned authorized representative of the Division of Oil, Gas & Mining has conducted an inspection of above mine on above date and has found violation(s) of the act, regulations or required permit condition(s) listed in attachment(s). This notice constitutes a separate Notice of Violation for each violation listed.

You must abate each of these violations within the designated abatement time. You are responsible for doing all work in a safe and workmanlike manner.

The undersigned representative finds that **cessation of mining** is ☐ **is not** ☒ expressly or in practical effect required by this notice. For this purpose, "mining" means extracting coal from the earth or a waste pile, and transporting it within or from the mine site.

This notice shall remain in effect until it expires as provided on reverse side of this form, or is modified, terminated or vacated by written notice of an authorized representative of the director of the Division of Oil, Gas & Mining. Time for abatement may be extended by authorized representative for good cause, if a request is made within a reasonable time before the end of abatement period.

Date of service/mailling MARCH 5, 1986Time of service/mailling 3:45☐ a.m.☒ p.m.CHARLES GENT

Permittee/Operator representative

Title _____

VIOLATIONS ISSUED FROM DIVISION OFFICE

Signature

DAVID LOF

Division of Oil, Gas & Mining representative

Signature

MINING FIELD SPECIALIST

Title

Identification Number #4

SEE REVERSE SIDE

WHITE-DOGM YELLOW-OSM PINK-PERMITTEE/OPERATOR GOLDENROD-NOV FILE

DOGM/NOV-1

an equal opportunity employer

11/85

notice of violation

4/01



NOTICE OF VIOLATION NO. N86-4-1-4

Violation No. 1 of 4

Nature of violation

FAILURE TO MINIMIZE EROSION TO THE EXTENT POSSIBLE
FAILURE TO STABILIZE AND PROTECT ALL SURFACE AREAS AFFECTED BY MINING TO
EFFECTIVELY CONTROL EROSION

Provisions of act, regulations or permit violated

UMCB17.45
UCA 40-10-17(2)(d)

Portion of operation to which notice applies

THE OUTSLOPE OF THE FILL FROM THE GENERATOR WEST TO APPROXIMATELY
100-150 FEET TO THE STREAM BUFFER ZONE SIGN.

Remedial action required (including any interim steps)

A. RESEED THE ~~THE~~ AREA USING AN APPROVED INTERIM SEED MIX.
B. MULCH THE AREA AND ANCHOR THE MULCH. RECOMMEND USING
2500-3000[#]/S OF STRAW /ACRE ~~AND~~ ANCHORED IN PLACE BY POLYPROPYLENE
NETTING STAPLED IN PLACE ON 3 FOOT CENTERS. ~~II~~

IF THE OPERATOR WISHES TO DEViate FROM WHAT IS RECOMMENDED THEN
PROPOSED PLANS MUST BE SUBMITTED FOR APPROVAL BY THE DIVISION AND IMPLEMENTED
UPON APPROVAL.

Abatement time (including interim steps)

A+B. A NO LATER THAN APRIL 15, 1986 AT 5pm

NOTE: IF AN ALTERNATE METHOD IS TO BE USED PLANS MUST BE SUBMITTED
BY MARCH 21, 1986



NOTICE OF VIOLATION NO. N 86-4-1-4

Violation No. 2 of 4

Nature of violation

FAILURE TO MINE IN ACCORDANCE WITH AN APPROVED PERMANENT PERMIT
FAILURE TO MAINTAIN CLASS I & II ROADS TO HAVE ADEQUATE DRAINAGE
AND MEET APPROVED DESIGN SPECIFICATIONS
FAILURE TO CONTROL OR MINIMIZE EROSION AND SILTATION TO THE EXTENT
POSSIBLE

Provisions of act, regulations or permit violated

~~HMA~~ UCA 40-10-17(2)(g)
UMC 771.19
UMC 817.150(a), .153(a)(1), .155(a)+(b), .160(a), .163(a)(1), .165(a)+(b)
UMC 817.45

Portion of operation to which notice applies

ALL ROADS IN THE PERMIT AREA

Remedial action required (including any interim steps)

MAINTAIN THE ROADS TO DESIGN SPECIFICATIONS I.E. CULVERTS, DITCHES,
ROAD SURFACE SLOPE, INSTALL GUARD RAILS AS SPECIFIED, ETC.

Abatement time (including interim steps)

A. CULVERTS & DITCHES MAINTAINED BY MARCH 12, 1986, 5 PM
B. ROAD SURFACE MAINTAINED BY APRIL 5, 1986 AT 5 PM
C. INSTALL GUARD RAILS BY MAY 5, 1986 AT 5 PM



NOTICE OF VIOLATION NO. N 86-4-1-4

Violation No. 3 of 4

Nature of violation

FAILURE TO MINE IN ACCORDANCE WITH AN APPROVED PERMIT

Provisions of act, regulations or permit violated

UMC 771.19

Portion of operation to which notice applies

OIL & GAS STORAGE AREA BERM

Remedial action required (including any interim steps)

CONSTRUCT A FUEL STORAGE ^{OVERFLOW} ~~CONTAINMENT~~ BERM IN ACCORDANCE WITH THE "TYPICAL SECTION" SHOWN IN DRAWING NO. G01-C-024 OF THE APPROVED MINE PLAN

Abatement time (including interim steps)

MARCH 19, 1986 AT 5pm.



NOTICE OF VIOLATION NO. N86-41-1-4

Violation No. 4 of 4

Nature of violation

FAILURE TO PASS ALL SURFACE DRAINAGE FROM THE DISTURBED AREA
THROUGH THE SEDIMENT POND

Provisions of act, regulations or permit violated

UMC 817.4/2(a)(1)

Portion of operation to which notice applies

DISTURBED AREA RUNOFF BYPASSING THE SEDIMENT POND INLET CULVERT
AND CONTINUING DOWN THE ROAD

Remedial action required (including any interim steps)

CONSTRUCT A WATER BAR ACROSS THE ACCESS ROAD EAST OF THE SEDIMENT
POND INLET CULVERT IN ORDER TO INSURE THAT ANY RUNOFF WHICH BYPASSES
THE CULVERT IS DIRECTED INTO THE SEDIMENT POND AND DOES NOT
CONTINUE DOWN THE ROAD

Abatement time (including interim steps)

IMMEDIATELY